

Comments	Vs	Conditions	Security Checks	Samples					
				Visual Check	SS	NH	P	Other Specify	PE Temp °C
Scraper reattached and tested system left off treatment informed PST 3 Flow back on PST 1=2.2m . PST 2=2.2m.	160	DS	OK	SC	S	0.46	1.2	<u>iron</u> 0.49	16.3
Reset S&F panel and back washed cell 2. PST 3 auto de-sludge back in auto.		O/cast	OK	PF	40	0.54	1.6	<u>iron</u> 0.28	16.3
Emailed [REDACTED] to re-order Ferric delivery.	110	Sunny dry	OK	PF	S	0.77	1.5	<u>iron</u> 0.38	19.1
INLET CHANNEL HOLDING BACK AGAIN. PST 1, 2 + 3 TOOK 40M TO DESLUDGE. MAKE SURE THESE ARE THOROUGHLY DESLUGGED TO WATER PUMP. FINISHED LOAD INSP.	103	O/CAST MUGGY	OK	FF	LS	0.19			18.5
DESLUGGED PST'S - VERY THICK	109	O/CAST MUGGY	OK	FF	LS	0.39			18.7